

ISC VALVE UNITS AND CLAIMS.

GSX-R1000K7

JZ

VIN COMPLETED

JS1GT77A772111750

JS1GT77A072111766

JS1GT77A272111767 COMPLETED

JS1GT77A472111768 COMPLETED

JS1GT77A672111769 COMPLETED

JS1GT77A272111770

JS1GT77A672111772 COMPLETED

JS1GT77A872111773 COMPLETED

JS1GT77AX72111774 COMPLETED

JS1GT77A172111775 COMPLETED

JS1GT77A572112556 COMPLETED

JS1GT77A372112779 COMPLETED

JS1GT77A372112801 COMPLETED

JS1GT77A472112838 COMPLETED

JS1GT77A672112839 COMPLETED

JS1GT77A272112840 COMPLETED

JS1GT77A472112841 COMPLETED

JS1GT77A872112843 COMPLETED

JS1GT77AX72112844

JS1GT77A172112845

JS1GT77A372112846 COMPLETED

JS1GT77A572112847 COMPLETED

JS1GT77A772112848 COMPLETED

JS1GT77A972112849 COMPLETED

JS1GT77A572112850 COMPLETED

JS1GT77A772112851

JS1GT77A972112852 COMPLETED

JS1GT77A072112853 COMPLETED

JS1GT77A272112854 COMPLETED

JS1GT77A472112855 COMPLETED

JS1GT77A672112856 COMPLETED

JS1GT77A872112857 COMPLETED

JS1GT77AX72112858 COMPLETED

JS1GT77A172112859 COMPLETED

JS1GT77A872112860 COMPLETED

JS1GT77AX72112861 COMPLETED

JS1GT77A172112862

JS1GT77A372112863 COMPLETED

JS1GT77A572112864

JS1GT77A972112866 COMPLETED

JS1GT77A872114110 COMPLETED

JS1GT77A372114113 COMPLETED

JS1GT77A572114114

JS1GT77A772114115 COMPLETED

JS1GT77A272114118

JS1GT77A472114119

JS1GT77A272114121 COMPLETED

JS1GT77A472114122 COMPLETED

JS1GT77A672114123 COMPLETED

JS1GT77AX72114125 COMPLETED

Suzuki New Zealand is conducting a safety recall on the listed GSX-R1000K7 motorcycle units. The customer service campaign is so we can replace the ISC control valve and the ECM to improve engine idle.

If the listed vin number has completed beside it no further action is needed. If however it is not completed, please contact your Suzuki dealer to arrange for repair at no charge.

JS1CL111100100059 COMPLETED
JS1CL111100100065 COMPLETED
JS1CL111100100066 COMPLETED
JS1CL111100100067 COMPLETED
JS1CL111100100068 COMPLETED
JS1CL111100100069 COMPLETED
JS1CL111100100070 COMPLETED
JS1CL111100100071
JS1CL111100100072 COMPLETED
JS1CL111100100073 COMPLETED
JS1CL111100100074 COMPLETED
JS1CL111100100077 COMPLETED
JS1CL111100100078 COMPLETED
JS1CL111100100079 COMPLETED
JS1CL111100100080 COMPLETED
JS1CL111100100090 COMPLETED
JS1CL111100100093
JS1CL111100100095
JS1CL111100100966 COMPLETED
JS1CL111100100967 COMPLETED
JS1CL111100100968 COMPLETED
JS1CL111100100969 COMPLETED
JS1CL111100102076 COMPLETED
JS1CL111100102077
JS1CL111100102078 COMPLETED
JS1CL111100102079 COMPLETED
JS1CL111200100308 COMPLETED
JS1CL111200100309 COMPLETED
JS1CL111200100310
JS1CL111200100311 COMPLETED
JS1CL111200100312 COMPLETED
JS1CL111200100313 COMPLETED
JS1CL111200100314
JS1CL111200100315
JS1CL111200100316 COMPLETED
JS1CL111200100317 COMPLETED
JS1CL111200100318 COMPLETED
JS1CL111200100319 COMPLETED
JS1CL111200100320 COMPLETED
JS1CL111200100321 COMPLETED
JS1CL111200100322 COMPLETED
JS1CL111200100323 COMPLETED
JS1CL111200100324 COMPLETED
JS1CL111200100325 COMPLETED
JS1CL111200100326 COMPLETED
JS1CL111200100327 COMPLETED
JS1CL111200100328 COMPLETED
JS1CL111200100329 COMPLETED
JS1CL111200100330
JS1CL111200100331 COMPLETED
JS1CL111200100332 COMPLETED
JS1CL111200100333
JS1CL111200100334
JS1CL111200100335 COMPLETED
JS1CL111200100336 COMPLETED
JS1CL111200100337 COMPLETED

JS1CL111200100338 COMPLETED
JS1CL111200100339 COMPLETED
JS1CL111200100340 COMPLETED
JS1CL111200100341 COMPLETED
JS1CL111200100342
JS1CL111200100343
JS1CL111200100344 COMPLETED
JS1CL111200100345 COMPLETED
JS1CL111200100346 COMPLETED
JS1CL111200100347 COMPLETED
JS1CL111200100348 COMPLETED
JS1CL111200100349 COMPLETED
JS1CL111200100350 COMPLETED
JS1CL111200100351 COMPLETED
JS1CL111200100413 COMPLETED
JS1CL111200100427
JS1CL111200100454 COMPLETED
JS1CL111200100455
JS1CL111200100476 COMPLETED
JS1CL111200100477 COMPLETED
JS1CL111200100478
JS1CL111200100479 COMPLETED
JS1CL111200100480 COMPLETED
JS1CL111200100481 COMPLETED
JS1CL111200100482
JS1CL111200100483
JS1CL111200100484 COMPLETED
JS1CL111200100485 COMPLETED
JS1CL111200100486
JS1CL111200100487
*** END OF REPORT ***

□